

SECTION 9

Pilot's Operating Handbook Supplement AS-10

Garmin GMA 350(c) Audio Panel



This supplement is applicable and must be inserted into Section 9 of the Pilot's Operating Handbook when a Garmin GMA 350(c) Audio Panel is installed in the AQUILA AT01-100/200. The information in this supplement adds to or replaces information in the basic Pilot's Operating Handbook.

Revision A.04 of AFM Supplement AS-10 ref. FM-AT01-1010-249 is approved under the authority of DOA ref. EASA.21J.025.

02.03.2020 
Date, Signature Office of Airworthiness

Document No.:	Issue:	supersedes Issue:	Date:	Page:
FM-AT01-1010-249	A.04	A.03 (01.06.2018)	02.03.2020	AS-10-1



0.1 RECORD OF REVISIONS

Issue	Reason for Change	Effected Pages	Date of Issue
A.01	Initial Issue	All	28.05.2013
A.02	Editorial Changes	All	15.10.2013
A.03	GMA 350c (Bluetooth) added	All	01.06.2018
A.04	also valid for AT01-200	All	02.03.2020

0.2 LIST OF CURRENT PAGES

Page	Issue	Date
1 - 4	A.04	02.03.2020

Page	Issue	Date

0.3 TABLE OF CONTENTS

1.	GENERAL.....	3
2.	OPERATING LIMITATIONS	3
3.	EMERGENCY PROCEDURES.....	3
4.	NORMAL PROCEDURES	3
5.	PERFORMANCE	4
6.	WEIGHT AND BALANCE.....	4
7.	SYSTEMS DESCRIPTION.....	4
8.	HANDLING, SERVICE AND MAINTENANCE	4

Document No.:	Issue:	supersedes Issue:	Date:	Page:
FM-AT01-1010-249	A.04	A.03 (01.06.2018)	02.03.2020	AS-10-2

1. GENERAL

The aircraft is equipped with a GMA 350(c) Audio Panel.

For a detailed description and full operating instructions please refer to the current issue of the GARMIN GMA 350(c) Pilot's Guide.

NOTE

The current issue of the GARMIN GMA 350(c) Pilot's Guide must be kept on board the aircraft and be available to the crew at all times.

2. OPERATING LIMITATIONS

The operating limitations of the basic POH apply without any changes or restrictions.

NOTE

Bluetooth/WiFi functionality of the GMA 350(c) Audio Panel is currently approved only for ground operation in the AQUILA and therefore in-flight activation is prohibited.

3. EMERGENCY PROCEDURES

Should the audio panel fail, the audio system automatically connects the pilot's head-set to COM 1, ensuring that he can continue to receive and transmit.

If necessary, the audio panel can be shut down by pulling the **AUDIO** circuit breaker.

4. NORMAL PROCEDURES

For a detailed description and full operating instructions, please refer to the current issue of the GARMIN GMA 350(c) Pilot's Guide.

CAUTION

The GMA 350(c) must be switched off during engine start-up and shut-down with the Avionics Master Switch set OFF.

Non-compliance could destroy the system. All warranty and guarantee claims will become void.

Document No.:	Issue:	supersedes Issue:	Date:	Page:
FM-AT01-1010-249	A.04	A.03 (01.06.2018)	02.03.2020	AS-10-3



5. PERFORMANCE

There is no change regarding the information in the basic Pilot's Operating Handbook.

6. WEIGHT AND BALANCE

There is no change regarding the information in the basic Pilot's Operating Handbook.

7. SYSTEMS DESCRIPTION

Functions and Operation

The GMA 350(c) Audio Panel offers the classical selection functions for microphone and receiver. In addition, it includes an intercom system (ICS), a marker beacon receiver and a COM recorder.

For a detailed description and full operating instructions, please refer to the current issue of the GARMIN GMA 350(c) Pilot's Guide.

Electrical protection for the GMA 350(c) Audio Panel

The GMA 350(c) is attached to the avionics bus and can be shut down by pulling the circuit breaker **AUDIO**.

8. HANDLING, SERVICE AND MAINTENANCE

There is no change regarding the information in the basic Pilot's Operating Handbook.

<i>Document No.:</i>	<i>Issue:</i>	<i>supersedes Issue:</i>	<i>Date:</i>	<i>Page:</i>
FM-AT01-1010-249	A.04	A.03 (01.06.2018)	02.03.2020	AS-10-4