

SERVICE LETTER

Change of designation of service documents

ATA System: 00-00-00 General

1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

1.1) Applicability

All versions of EASA certified ROTAX engine types including all serial numbers.

All versions of ASTM compliant ROTAX engine types including all serial numbers.

Already issued service documents remain effective and will keep the old numbering system in case of necessary revisions.

1.2) Concurrent ASB/SB/SI and SL

None.

1.3) Reason

A new numbering system for future documentation is introduced in January 2026.

The new designation is structured as follows:

e.g. **SL** - **2026** - **001** **R01**

 Type Year Number Revision

Designation		Description
Document type	ASB	Alert Service Bulletin for EASA certified engines
	ASB_A	Alert Service Bulletin for ASTM engines
	SB	Service Bulletin for EASA certified engines
	SB_A	Service Bulletin for ASTM engines
	SI	Service Instruction
	SI-PAC	Service Instruction - Parts and Accessories
	SL	Service Letter
Year	20XX	4 digit year of initial document release
Number	00X	3 digit consecutive number that re-sets to 001 each calendar year. Each document type has its own numbering designation.
Revision	R0X	2 digit consecutive number for revisions

NOTE: Engine types will no longer be listed in the document designation.

1.4) Subject

Change of designation of service documents.

d07255.fm

SERVICE LETTER

1.5) Compliance

NONE - For Information Only

1.6) Approval

The technical content of this document is approved under the authority of the DOA ref. EASA.21J.048.

For ASTM compliant engines the technical content of this document is approved under the relevant processes of the effective BRP-Rotax quality management system.

Content concerning certified engine types also applies to ASTM compliant engine types.

2) Additional Information

2.1) Inquiries

Inquiries regarding this Service Letter should be sent to the ROTAX® Authorized Distributor of your area.

A list of all ROTAX® Authorized Distributors or their independent Service Centers is provided on <https://dealerlocator.flyrotax.com>.

SERVICE LETTER

3) Appendix

3.1) Examples of designation

3.1.1) The illustration below shows the old designation (1) of service documents:




Fig. 1
Old designation

3.1.2) The illustration below shows the new designation (2) of service documents for EASA certified engines:




Fig. 2
New designation

SERVICE LETTER

3.1.3) The illustration below shows the new designation (3) of service documents for ASTM engines:




Fig. 3
New designation for ASTM engines

NOTE: The illustrations in this document show the typical construction. They may not represent full detail or the exact shape of the parts which have the same or similar function. Exploded views are not technical drawings and are for reference only. For specific detail, refer to the current documents of the respective engine type.